

# RG59 MINI QUICK STEPS



## Calibrate Cable

Once the cable is prepared, connect VoD unit then press and hold the ON/OFF button for 8 seconds. This process will take around 5 mins.

## Cable Installation

Disconnect the VoD unit, as you pull cable the end with the BNC connector will spin.

## Cable Installation following holes

For the following holes, the cable must be looped down and back up the hole, record the meter markers in and out of the holes, leaving slack in-between holes.

For further queries get in touch:  
[info@shottrack.com.au](mailto:info@shottrack.com.au)

**SHOTTRACK**

STEP  
01

STEP  
02

STEP  
03

STEP  
04

STEP  
05

STEP  
06




## Check Settings

Once calibrated, make sure the unit reads approximately 305m.

## Cable Installation First hole

The end of the cable must be looped at least 3 meters, then lowered down the first fired hole.



## Connect and Set

Before the blast, connect VoD unit, turn on device, make sure it reads approximately 305m. The unit will arm itself after a few minutes.

